

No 0 = TRES RUDE VERY HARD MUY FUERTE	No 1 = RUDE HARD FUERTE	No 2 = MI-RUDE SEMI-HARD SEMI-FUERTE	No 3 = MI-DOUX SEMI-SOFT SEMI-SUAVE	No 4 = DOUX SOFT SUAVE
---	-------------------------------	--	---	------------------------------

BROSSES A MAINS POUR MONTRES  
HAND BRUSHES FOR WATCHES  
CEPILLOS DE MANO PARA RELOJES

Glasgow



Rangs Rows Hileras	No: 0	No: 1	No: 2	No: 3	No: 4
3	192-300	192-301	192-302	192-303	192-304
4	192-400	192-401	192-402	192-403	192-404

BROSSES POUR PENDULES  
BRUSHES FOR CLOCKS  
CEPILLOS PARA PENDULOS

Rangs Rows Hileras	Crins blancs White bristles Crin blanco
5	No 194-001
6	No 194-002

BROSSES EN FILS D'ACIER & LAITON  
BRUSHES WITH BRASS & STEEL WIRES  
CEPILLOS DE HILOS DE ACERO & LATON

FILS ACIER - STEEL WIRES - HILERAS DE ACERO				
Rangs Rows Hileras		Ø fils - Ø wires - Ø hilos		
		0.08	0.10	0.15
4		No 195-008	No 195-010	No 195-015
FILS LAITON - BRASS WIRES - HILOS DE LATON				
4		No 196-008	No 196-010	No 196-015